

Listed Buildings in West Chiltington

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>BARN AT DENNIS MARCUS FARM TO NORTH WEST OF THE FARMHOUSE</u>	Grade: II	BARN AT DENNIS MARCUS FARM TO NORTH WEST OF THE FARMHOUSE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	C18. Faced with weatherboarding. Hipped tiled roof.
<u>BARN AT NALDRETT'S FARM TO NORTH EAST OF THE FARMHOUSE</u>	Grade: II	BARN AT NALDRETT'S FARM TO NORTH EAST OF THE FARMHOUSE, EAST STREET, West Chiltington, Horsham, West Sussex	C17 timber-framed building with painted brick infilling, the first floor level now faced with weather-boarding. Hipped roof now of corrugated iron.
<u>BARN AT OLDHOUSE FARM TO NORTH EAST OF THE HOUSE</u>	Grade: II	BARN AT OLDHOUSE FARM TO NORTH EAST OF THE HOUSE, OLD HOUSE LANE, COOLHAM, West Chiltington, Horsham, West Sussex	C17. Faced with weather-boarding. Steeply-pitched tiled roof. Wagon entrance on north side.
<u>BLOUNTS</u>	Grade: II	BLOUNTS, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed cottage with roughcast infilling restored and enlarged, the ground floor rebuilt in brick, now painted. Tiled roof. Modern gable in centre. Modern casement windows. Two storeys. Two windows. Modern wing behind.
<u>BROADFORD BRIDGE FARMHOUSE</u>	Grade: II	BROADFORD BRIDGE FARMHOUSE, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier. Two storeys. Three windows. Now faced with coursed Hythe sandstone. Hipped Horsham slab roof. Casement windows. Stone chimney breast at west end.
<u>BROOK HOUSE FARMHOUSE</u>	Grade: II	BROOK HOUSE FARMHOUSE, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	Probably C17, two storeys. Four windows. Now stuccoed. C19 two storeyed projection in centre containing porch with room over. Hipped slate roof. Casement windows.
<u>CHURCH HOUSE</u>	Grade: II	CHURCH HOUSE, CHURCH STREET, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building refronted in the C18. Two storeys and basement above ground level. Three windows. Paced with stone rubble. Tile roof. Glazing bars intact.
<u>CLARKES COTTAGE</u>	Grade: II	CLARKES COTTAGE, CHURCH STREET, West Chiltington, Horsham, West Sussex	Now one dwelling. C17 or earlier building, refaced with brick and stone, now painted but the timbering still visible in north wall. Steeply-pitched hipped tiled roof. Casement windows. Two storeys. Three windows.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>CLAYES FARMHOUSE</u>	Grade: II	CLAYES FARMHOUSE, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building with timbering exposed in north wall but refronted with painted brick. Modillion eaves cornice. Hipped tiled roof. Casement windows. Two storeys. Four windows.
<u>COMFREY, COLLHAM</u>	Grade: II	COMFREY, COLLHAM, COOLHAM, West Chiltington, Horsham, West Sussex	C17 or earlier. Two storeys. Four windows. Now faced with red brick and stone rubble. Tiled roof. Casement windows. A portion has been built out in front of the west half on ground floor only.
<u>CONEYHURST FARMHOUSE</u>	Grade: II	CONEYHURST FARMHOUSE, WEST CHILTINGTON LANE, West Chiltington, Horsham, West Sussex	C17. Two parallel ranges Two storeys. Two windows. Ground floor now red brick and grey headers, above faced with weather-boarding at the front with tile-hanging at the sides. Horsham slab roof in two hins. Casement
<u>CROWELL FARMHOUSE</u>	Grade: II	CROWELL FARMHOUSE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	L-shaped house. Back wing C17 or earlier. Two storeys. Three windows. Stone rubble. Tiled roof. Casement windows. Front wing early C19 and has a higher elevation. Two storeys. Three windows. Red brick. Hipped tiled roof. Glazing bars intact. Doorway with reeded pilasters, flat hood over and six panel door.
<u>DAUX FARMHOUSE</u>	Grade: II	DAUX FARMHOUSE, MILL ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed cottage with plaster infilling, enlarged by the addition of a T-wing behind. Tiled roof. Casement windows. Two storeys. Three windows.
<u>DENNIS MARCUS FARMHOUSE</u>	Grade: II	DENNIS MARCUS FARMHOUSE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	Long C18 building of coursed stone with some red brick and tile-hanging at south end. Tiled roof. Casement windows. Doorway with flat hood over on brackets. Two storeys. Five windows.
<u>FRYARS</u>	Grade: II	FRYARS, MILL ROAD, West Chiltington, Horsham, West Sussex	Originally called Barnetts Farm. C17 or earlier. Stone rubble with red brick dressings, quoins and stringcourse. Horsham slab roof. Gable at north-east end of front. Casement windows. Doorway with flat hood over and, above this, shell ornament. Elaborately carved door. Two storeys and attic in gable. Three windows.
<u>GATEWICK FARMHOUSE</u>	Grade: II	GATEWICK FARMHOUSE, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed house refronted with red brick and stone on ground floor but with some timbering and plaster infilling exposed above. Tiled roof. Casement windows. Two storeys. Four windows. Modern addition to east.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>GAYSTREET FARMHOUSE</u>	Grade: II	GAYSTREET FARMHOUSE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	C18. Two parallel ranges. Two storeys. Three windows. Red brick and grey headers alternately. Stringcourse. Horsham slab roof. Casement windows. Doorway with flat hood on brackets.
<u>GAYWOOD FARMHOUSE</u>	Grade: II	GAYWOOD FARMHOUSE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	Two parallel ranges. Front range C17 or earlier timber-framed with plaster infilling but restored and enlarged and its south side refaced with stone. Tiled roof. Casement windows. Modern bays. Two storeys and attic. Three windows. One hipped dormer. Back range C18 and stone. To the south a modern L-wing has been added in red brick and imitation timbering.
<u>GENTLE HARRYS FARMHOUSE</u>	Grade: II	GENTLE HARRYS FARMHOUSE, MILL ROAD, West Chiltington, Horsham, West Sussex	Restored C18 house. Two storeys. Four windows. Red brick, grey headers and stone rubble. Stringcourse. Half-hipped tiled. Casement windows.
<u>HAYLING POND COTTAGE</u>	Grade: II	HAYLING POND COTTAGE, CHURCH STREET, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building with plaster infilling, largely refaced with stone. Hipped tiled roof. Casement windows. One storey and attic. Three windows. Three gabled dormers.
<u>HOBJOHNS</u>	Grade: II	HOBJOHNS, 1 AND 2, CHURCH STREET, West Chiltington, Horsham, West Sussex	C18, south end added later. Two storeys. Four windows. Stone rubble, south end cemented. Tiled roof. Casement windows. (Ground value).
<u>HOBJOHNS CROFT</u>	Grade: II	HOBJOHNS CROFT, CHURCH STREET, West Chiltington, Horsham, West Sussex	House. C16 or earlier timber-framed building with exposed timberframe to the side elevation, refaced in late C18 or early C19 in stone and brick to front elevation. Hipped tiled roof with gablets and off central brick chimneystack. Two storeys: three windows. Casement windows, with cambered head linings to ground floor and cambered doorcase opposite chimneystack.
<u>HOLDERS COTTAGE</u>	Grade: II	HOLDERS COTTAGE, WEST CHILTINGTON LANE, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed cottage with plaster infilling, ground floor rebuilt in brick, now painted. Tiled roof. Casement windows. Two storeys. Three windows.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>HORELANDS</u>	Grade: II	HORELANDS, WEST CHILTINGTON LANE, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building with the timbering exposed with painted brick infilling in north wall but refaced with brick, not painted, on ground floor and tile-hung above. Hipped tiled roof. Casement windows. Two storeys. Three windows.
<u>HUNTERS BARN</u>	Grade: II	HUNTERS BARN, THE HOLLOWES, West Chiltington, Horsham, West Sussex	C18. Two storeys. Two windows. Faced with weather-boarding on a stone base. Hipped tiled roof. Modern windows. Group value.
<u>HUNTLEYS</u>	Grade: II	HUNTLEYS, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building with plaster infilling, mostly rebuilt in brick, now painted and stone rubble. Tiled roof. Casement windows. Two storeys. Two windows.
<u>JESSAMINE COTTAGE</u>	Grade: II	JESSAMINE COTTAGE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	Restored C17 or earlier timber-framed cottage with plaster infilling and one window bay added at south end in stone. Tiled roof. Casement windows. One blocked original window of six lights with wooden mullions. Two storeys. Three windows.
<u>KINGS AND PRINCESS FARMHOUSE</u>	Grade: II	KINGS AND PRINCESS FARMHOUSE, THE HOLLOWES, West Chiltington, Horsham, West Sussex	C18. Two storeys. Two windows. Stuccoed front on base of stone rubble. Half-hipped Horsham slab roof. Glazing bars intact. Doorway up seven steps with flat hood over.
<u>LAKERS CROFT</u>	Grade: II	LAKERS CROFT, THE HOLLOWES, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed house, refaced with ashlar, now painted, but with the timbering visible in the east wall with painted brick infilling. Tiled roof. Casement windows. Two storeys. Three windows.
<u>LAKERS FARM COTTAGE</u>	Grade: II	LAKERS FARM COTTAGE, MILL ROAD, West Chiltington, Horsham, West Sussex	C18. Two storeys. Five windows. Stone rubble with red brick dressings and ashlar quoins. Tiled roof. Casement windows.
<u>LAKERS FARMHOUSE</u>	Grade: II	LAKERS FARMHOUSE, MILL ROAD, West Chiltington, Horsham, West Sussex	Two parallel ranges. Front range timber-framed, refaced with stone rubble with red brick dressings and quoins but the timbering with plaster infilling visible in north-east wall. Tiled roof. Sash windows with glazing bars intact. Doorway with flat hood over. Two storeys. Three windows. Back range C18 or later.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>LINTOTTS</u>	Grade: II	LINTOTTS, GAY STREET LANE, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed cottage with plaster infilling. Thatched roof. Casement windows. Two storeys. Two windows.
<u>LOWER JORDANS FARMHOUSE</u>	Grade: II	LOWER JORDANS FARMHOUSE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed house refronted with stone rubble but with the timbering and plaster infilling exposed at the back. Tiled roof. Casement windows. Blocked original widow with wooden millions in the half-hipped gable end. Two storeys. Four windows.
<u>MALTHOUSE COTTAGE</u>	Grade: II	MALTHOUSE COTTAGE, MILL ROAD, West Chiltington, Horsham, West Sussex	Early C19. Two storeys. Two windows. Stone rubble with red brick dressings and ashlar quoins. Tiled roof. Casement windows.
<u>MAWKINS</u>	Grade: II	MAWKINS, MILL ROAD, West Chiltington, Horsham, West Sussex	Restored C17 or earlier timber-framed building with plaster infilling. Tiled roof with two "eyebrows". Modern casement windows. Two storeys. Three windows.
<u>MEERS FARMHOUSE</u>	Grade: II	MEERS FARMHOUSE, THE HOLLOWES, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building with the timbering exposed in the north-west wall but now faced with plaster. Horsham slab roof. Casement windows. Two storeys. Three windows.
<u>MILL HOUSE</u>	Grade: II	MILL HOUSE, MILL ROAD, West Chiltington, Horsham, West Sussex	Early-mid C19. Two storeys. Two windows. Coursed stone with red brick dressings and quoins. Slate roof. Glazing bars intact. Modern porch.
<u>MITCHELLS</u>	Grade: II	MITCHELLS, CHURCH STREET, West Chiltington, Horsham, West Sussex	C18. Three parallel ranges. Two storeys. Two windows. Stone rubble with red brick dressings and quoins. Tiled roof. Glazing bars intact.
<u>NALDRETT'S FARMHOUSE</u>	Grade: II	NALDRETT'S FARMHOUSE, EAST STREET, West Chiltington, Horsham, West Sussex	C16 or earlier timber-framed house with painted brick infilling and curved braces on first floor. Steeply-pitched hipped tiled roof. Casement windows. Two storeys. Four windows.
<u>NEWHOUSE FARMHOUSE</u>	Grade: II	NEWHOUSE FARMHOUSE, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier L-shaped house refronted with cement, but the east wall coursed stone. Tiled roof. Casement windows. Two storeys. Three windows.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>NYETIMBER</u>	Grade: II	NYETIMBER, GAY STREET LANE, West Chiltington, Horsham, West Sussex	C17 or earlier L-shaped timber-framed building with plaster infilling with the timbering exposed in the east wing but otherwise refaced with stone. Horsham slab roof. Gable with attic window to east wing. Modern casement windows. Two storeys. Five windows. Modern addition to south in stone with tiled roof.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>NYETIMBER FARM BARN</u>	Grade: II	NYETIMBER FARM BARN, LOWER JORDANS LANE, West Chiltington, Horsham, West Sussex	<p>Barn, in three parts, with a primary construction date of C15, which has been extended, remodelled and repaired throughout its history.</p> <p>Nyetimber Farm Barn can be considered as three components: Medieval (north) Barn, Middle Barn and South Barn. This description uses these distinctions to provide a more accurate depiction of the building.</p> <p>MATERIALS: Oak-framed, with weather-boarding and clay tile roof covering to the Medieval and Middle Barn, and skeletal to the South Barn. All on a rubble stone plinth. Drilled dowel holes indicate that the walls of the Medieval Barn were initially fully infilled with wattle-and-daub, as were the upper parts of the Southern Barn, although the lower walls were weather-boarded. Thin dark stains on the underside of some of the rafters in the Medieval Barn and South Barn indicated that the former roof covering was thatch.</p> <p>MEDIEVAL BARN Plan: The original, C15, oak-framed, three-bays of the Medieval Barn measure 12.85m by 6.76m; the northern c.1700 bay 3.95m. The reconstructed western aisle measures 1.85m wide, giving an overall width of 8.6m, and a length for the four bays and two end aisles of 23.8m.</p> <p>Exterior: The principal entrance is the full-height wagon doorway in the eastern façade; the opposing western wagon door has been blocked in timberwork. Two C20 single doors have been added, one each in the northern and southern elevations, the latter giving stepped access to the Middle Barn. There are no windows in the northern, eastern or southern elevations, but one per bay in the western aisle. These are unglazed and are of one or two lights with wooden mullions and glazing bars, situated directly under the wall-plate.</p> <p>Interior: The C15 walls comprise ogee-shaped passing braces that rise from the principal posts, half pass the side girt and are morticed-and-tenoned into the wallplate. The wall of the c1700 bay incorporates equally-spaced studs both above and below side-girt level. In the C20, braces have been added, to match those in the older wall. The timbers of the extensions are of an inferior finish to the C15 ones and in places bark has been retained. The medieval barn has a crown post roof and although heavily reconstructed, the crown posts and enough rafters survive to illustrate its original design. At the trusses the rafters are not set over the tie beams, but to one side. The collars (all of which have been removed) were halved to the rafters. The northern roof terminal was formerly hipped and the southern terminal is currently hipped, with the roof slope continuing down over the southern return aisle.</p>

NAME	HERITAGE CATEGORY LISTING	LOCATION	
			<p>However, this is a complete rebuild and it is possible that the southern terminal may originally have been gabled, particularly if the building originally abutted an earlier structure. The roof of the c1700 bay is of clasped-side-purlin construction, the northern terminal having a hipped end. The rear aisle originally had a roof of square-set butt-purlins, of which only three-bays now survive. Internally, the barn is open to the roof. The late C20 concrete floor is set 1.15m above that of the Middle barn.</p> <p>MIDDLE BARN Plan: Four-bay, single-storey barn, with a total width of 4.7m and length of 12.8m. Exterior: Of uncertain date, being much restored and rebuilt, probably c1800 and in the C20, the surviving original parts have a C17 appearance, though it may be that earlier material was reused in a c1800 rebuild. The external walls have been heavily rebuilt and now comprise regular-stud construction. There are three doorways into this barn. The principal entrance is a single-door in the third-bay of the eastern elevation. Secondary doors lead from the first-bay in the western elevation into the C20 lean-to, and up five brick and concrete steps in the north-east corner into the Medieval Barn. Windows have been inserted into the southern three bays of the western façade and northern three bays of the eastern façade. All but one are single-light unglazed windows with timber glazing bars; the other a three-light unglazed window with timber mullions and glazing bars; all are situated directly under the wall-plate. There is a C20 lean-to abutting the west of the Middle Barn, which currently acts as a bicycle shed and a C20 half-aisle to the southern end of the eastern side, under a catslide roof. Interior: The roof comprises clasped-side-purlin construction with raking struts supporting the purlins. Internally, the best preserved sections are the open trusses. These have standard principal posts with swelling jowls and incorporate relatively short arch braces (many replaced). The spur tie beams and principal posts at the southern truss project to both east and west of the earlier South Barn. The C20 concrete floor is considerably higher than that within the wagon bay of the South Barn, though this could be the result of later floor level changes.</p>

NAME	HERITAGE CATEGORY LISTING	LOCATION	
			<p>SOUTH BARN Plan: The three-bays of the skeletal oak framed South Barn measure 9.45m long and, for its height, is narrow at only 3.85m (with a total width including the east and west aisles of approximately 9m). In comparison, the height of the walls is also 3.85m.</p> <p>Exterior: Apart from the two-thirds height wagon doors in the eastern and western walls of the northern bay, the stud positions give no suggestion of other external ground-floor doorways. Set centre of the southern wall at the upper level is an area of tie beam absent of stave notches or grooves: this area may represent a hatch or loading doorway.</p> <p>Interior: The roof is of clasped-side-purlin and raking-strut construction with a hipped terminal to the south. The rafters are heavy and neat, the principal rafters being of equal scantling to those of the common rafters. The floor is currently uncovered. Although a little C17 original work may survive, the c1800 rebuilt and C20 restored Middle Barn is not of special interest in its own right.</p> <p>GROUP VALUE: Nyetimber Farm Barn, in its entirety, forms a group with the adjacent C17 or earlier L-shaped timber-framed farm house (listed at Grade: II) and associated buildings.</p>
<u>OLD HAGLANDS</u>	Grade: II	OLD HAGLANDS, HAGLANDS LANE, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building refronted with stone, now painted, but the timbering exposed at the back. Tiled roof. Casement windows. Buttress towards the west end of the front. Two storeys. Three windows.
<u>OLD YEW TREE COTTAGE</u>	Grade: II	OLD YEW TREE COTTAGE, HARBOLETS ROAD, West Chiltington, Horsham, West Sussex	C18 or earlier. Two storeys. Three windows. Faced with weather-boarding. Thatched roof with pentice at north-west end. Casement windows.
<u>OLDHOUSE FARMHOUSE</u>	Grade: II	OLDHOUSE FARMHOUSE, OLD HOUSE LANE, COOLHAM, West Chiltington, Horsham, West Sussex	Long medieval timber-framed building with the timbering exposed at the back but refronted with red brick and grey headers on ground floor and weather-boarding above. Tiled roof. Casement windows with diamond-shaped or small square panes. Two storeys. Six windows. Crown-post roof inside.
<u>PALMERS</u>	Grade: II	PALMERS, THE HOLLOWES, West Chiltington, Horsham, West Sussex	C18 or earlier. Two storeys on a high base. Three windows. Stone rubble. Hipped tiled roof. Casement windows. Modern porch up six steps.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>PALMERS</u>	Grade: II	PALMERS, WEST CHILTINGTON LANE, Billingshurst, Horsham, West Sussex	C18 or earlier. Two storeys on a high base. Three windows. Stone rubble. Hipped tiled roof. Casement windows. Modern porch up six steps.
<u>PALMERS LODGE</u>	Grade: II	PALMERS LODGE, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C18. Two Storeys. Three windows. Stone rubble with red brick dressings and quoins. Slate roof. Altered casement windows.
<u>PEACOCK TREE</u>	Grade: II	PEACOCK TREE, WEST CHILTINGTON ROAD, ROUNDABOUT, West Chiltington, Horsham, West Sussex	Early C19. Two storeys. Four windows. Stone rubble with red brick dressings and quoins. Slate roof. Casement windows.
<u>ROUNDABOUT FARMHOUSE</u>	Grade: II	ROUNDABOUT FARMHOUSE, WEST CHILTINGTON ROAD, ROUNDABOUT, Storrington and Sullington, Horsham, West Sussex	Probably C17. Two storeys. Five windows. Coursed stone with red brick dressings and quoins. Half-hipped tiled roof. Casement windows. Modern additions to east and north.
<u>SADDLERS</u>	Grade: II	SADDLERS, CHURCH STREET, West Chiltington, Horsham, West Sussex	Early C19 continuation of the stores. Two storeys. Three windows. Painted brick and stone. Slate roof. Casement windows.
<u>SAND POND COTTAGE</u>	Grade: II	SAND POND COTTAGE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	Restored C17 or earlier timber-framed cottage with plaster infilling and one window bay added at south end in stone. Tiled roof. Casement windows. One blocked original window of six lights with wooden mullions. Two storeys. Three windows.
<u>SEARLES</u>	Grade: II	SEARLES, 1 2 AND 3, CHURCH STREET, West Chiltington, Horsham, West Sussex	GV 2. L-shaped block. East wing C17 or earlier timber-framed building with red brick infilling. Tiled roof. Casement windows. Two storeys. Three windows. North-south wing early C19. Two storeys. Three windows. Red brick and grey headers alternately. Modillion eaves cornice. Tiled roof. Casement windows.
<u>SOLELANDS</u>	Grade: II	SOLELANDS, HARBOLETS ROAD, West Chiltington, Horsham, West Sussex	C17 building with the timbering and painted brick infilling exposed in north wall but refaced with roughcast. Tiled Roof. Casement windows. Two storeys. Three windows.
<u>SOUTHLAND FARMHOUSE</u>	Grade: II	SOUTHLAND FARMHOUSE, SOUTHLANDS LANE, West Chiltington, Horsham, West Sussex	C17 or earlier. Two storeys. Two windows. Coursed stone. Steeply-pitched hipped tiled roof with pentice to west half of front. Casement windows on ground floor, sash windows above with glazing bars intact.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>STEP HOUSE</u>	Grade: II	STEP HOUSE, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed house refaced with stone rubble with red brick dressings, quoins and stringcourse but with the timbering with plaster infilling exposed in the north wall. Half-hipped tiled roof. Modern casement windows. Two storeys and basement above ground level. Three windows.
<u>STILE HOUSE</u>	Grade: II	STILE HOUSE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed house with some painted brick and stone infilling, but restored and enlarged and largely refaced with stone, brick and weatherboarding, all painted. Tiled roof with one "eyebrow" over two windows. Casement windows. Two storeys. Three windows. One modern window-bay with painted gable over added at south end.
<u>STOCKS COTTAGE</u>	Grade: II	STOCKS COTTAGE, CHURCH STREET, West Chiltington, Horsham, West Sussex	C18. Two storeys, Three windows. Stone rubble, first floor of north end tile-hung. Tiled roof. Casement windows.
<u>THE ELEPHANT AND CASTLE INN</u>	Grade: II	THE ELEPHANT AND CASTLE INN, CHURCH STREET, West Chiltington, Horsham, West Sussex	C18. Two storeys. Two windows. Stone rubble with red brick dressings and quoins. Tiled roof. Glazing bars intact. Modern additions to south.
<u>THE FORGE COTTAGE</u>	Grade: II	THE FORGE COTTAGE, THE HOLLOWES, West Chiltington, Horsham, West Sussex	C18. Two storeys. Two windows. Hythe sandstone rubble. Tiled roof. Casement windows.
<u>THE OLD RECTORY</u>	Grade: II	THE OLD RECTORY, THE HOLLOWES, West Chiltington, Horsham, West Sussex	Early C19. Two storeys. Five windows, the outer ones twin windows. Painted brick. Hipped slate roof. Glazing bars intact. Venetian shutters. Pointed doorway with dripstone over.
<u>THE OLD SCHOOL HOUSE</u> <u>THE STONE HOUSE</u>	Grade: II	THE STONE HOUSE, CHURCH STREET, THE OLD SCHOOL HOUSE, CHURCH STREET, West Chiltington, Horsham, West Sussex	The former school (in 1977 in course of conversion into a dwelling) is dated 187? L-shaped building. South-east wing one storey with one large and one small gable. North wing two storeys with two gabled dormers. Small gabled projection at its north end. Stone. Tiled roof. Casement windows. Gabled porch. The Stone House was probably the schoolmaster's house originally. Same date, style and materials. Gable at south end. Gabled dormer to north. Porch with tiled roof. Two storeys. Two windows.

NAME	HERITAGE CATEGORY LISTING	LOCATION	
<u>THE PARISH CHURCH OF ST MARY</u>	Grade: I	THE PARISH CHURCH OF ST MARY, CHURCH STREET, West Chiltington, Horsham, West Sussex	Chancel with south chapel, nave with south aisle, central bell-turret with spire and north porch. Chancel and nave walls late C11, aisle late C12. King-post roof dated 1602, when the broached shingled spire was added. Horsham slab roof outside. Mural paintings of C12 and C14.
<u>THE POST OFFICE STORES</u>	Grade: II	THE POST OFFICE STORES, CHURCH STREET, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building refaced with brick and stone, now painted. Hipped tiled roof. Casement windows. Modern shop windows. Two storeys. Three windows.
<u>THE QUEENS HEAD INN</u>	Grade: II Grade: II	THE QUEENS HEAD INN, THE HOLLOWES, West Chiltington, Horsham, West Sussex	C18 front to a. probably earlier building, Two storeys. Three windows. Fronted with stone, painted. Brick modillion eaves cornice. Tiled roof. Casement windows. Portion built out in front of east half of ground floor.
<u>THE STABLES AT THE OLD RECTORY TO THE NORTH WEST OF THE HOUSE</u>	Grade: II	THE STABLES AT THE OLD RECTORY TO THE NORTH WEST OF THE HOUSE, THE HOLLOWES, West Chiltington, Horsham, West Sussex	Early C19. Stone rubble with red brick quoins. Slate roof. Centre portion of one storey and four windows. Flanking wings of trio storeys and one window each.
<u>THE WHIPPING POST AND STOCKS</u>	Grade: II	THE WHIPPING POST AND STOCKS, CHURCH STREET, West Chiltington, Horsham, West Sussex	Placed just outside the north-east corner of the churchyard in a small enclosure with iron railings.
<u>WALNUT TREE COTTAGE</u>	Grade: II	WALNUT TREE COTTAGE, GAY STREET LANE, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed cottage with plaster infilling on first floor of west wall, ground floor painted brick and stone, the whole of the front refaced in red brick and grey headers. Steeply-pitched hipped tiled roof. Casement windows. Two storeys. Three windows.
<u>WEST CHILTINGTON WINDMILL</u>	Grade: II	WEST CHILTINGTON WINDMILL, MILL ROAD, West Chiltington, Horsham, West Sussex	C18. Smock mill with octagonal "roundhouse" of Hythe sandstone rubble, tarred. First floor similar. Next two storeys faced with tarred weather-boarding. Boat-shaped cap. Only two sweeps intact. Residential additions to south-east - south-west.
<u>WOODS HILL HOUSE</u>	Grade: II	WOODS HILL HOUSE, BROADFORD BRIDGE ROAD, West Chiltington, Horsham, West Sussex	C17 or earlier timber-framed building of irregular shape, refaced with stone rubble. Tiled roof. Casement windows. Two storeys. Three windows. Additions to north.